

BOARD OF COMMISSIONERS OF PILOTS

I 7 BATTERY PLACE

NEW YORK, NY 10004 - 1207

TEL: 212 - 425-5027 FAX: 212 - 344-3144 CELL: 917-583-6373 WEBSITE/EMAIL: WWW.BDCOMMPILOTSNY.ORG

TO: SANDY HOOK PILOTS' ASSOCIATION HUDSON RIVER PILOTS' ASSOCIATION BLOCK ISLAND PILOT'S/SOUND PILOTS' ASSOCIATION

POLICY AND PROCEDURE NOTICE # 011706 YACHTS

The Board has reviewed its policy on foreign flag yachts entering or departing the ports and waters of New York State

All foreign flag yachts 100 feet in overall length and over shall be required to take a state pilot.

Vessels which fail to comply with the NY State Navigation Law are subject to statutory penalties.

Any foreign flat vessel, including yachts as specified above, failing to take a pilot shall also be reported to the USCG Captain of the Port of New York or USCG Captain of the Port of Long Island Sound.

BY ORDER OF THE BOARD

17January 2006

Robert H. Pouch Executive Director

CC: USCG, COTP NY USCG, COTP LIS